

Submission Date: February 2025

(Please remember that the HIP is for new initiatives/measures/schemes in your community – it is NOT to be used as a maintenance log, as these MUST be logged using the online reporting tool via this link https://www.kent.gov.uk/roads-and-travel/report-a-problem)

HIP Front Cover

HIP Version	(Name)	/	HIP Date	Record Of Meeting Dates with KCC Virtual or Face to Face			Please list below the funding Opportunities/Sources for HIP initiatives/Measures			
4	Irene B	Bowie	25/02/2025	7.04 20.1 21.0 28/0	0.22 7.23 – Primary	Sch	nool Meeting	Coun	ity Member, P	arish Precept Donation
Are you an active member of the Speed Watch Scheme?			No	Are you an active member of the Lorry Watch Scheme?			Yes □ No ⊠			
	Name of HIP Representative			Contact 07 Telephone Number		07788 278972	2	Email Address	clerk@coxheathparishcouncil.org.uk	
Name of	Name of Clerk			Contact Telephone Number		07788 278972	2	Email Address	clerk@coxheathparishcouncil.org.uk	
Name of Chair Gavin Crickett			Contact Telephone Number				Email Address	<u>chaiman@coxheathparishcouncil.org.</u> <u>uk</u>		
	KCC Project Manager Name		Contact Telephone Number				Email Address			

Please note the Priority column MUST be those issues which are regarded as the most important (No 1 being your highest priority, then filtering down) KCC is unable to guarantee that all your requests will be deliverable, but Project Managers can investigate your top 1 or 2 priorities per year.



Submission Date: February 2025

(Please remember that the HIP is for new initiatives/measures/schemes in your community – it is NOT to be used as a maintenance log, as these MUST be logged using the online reporting tool via this link https://www.kent.gov.uk/roads-and-travel/report-a-problem)

Live Priorities Record

Priority	Location	Problem/Concern	What do you feel are the potential solutions?	KCC Comments (This column is to be completed by Project Manager ONLY)
1.	HEATH ROAD Coxheath	Parking causing pedestrians to walk in the road, traffic jams etc	both sides of Heath Road. Two variants:	28/04/25 - Can the PC share any photos of the problem? 28/04/25 - PC inform that this is often overnight/evening parking, they think from residents of Clockhouse Rise, but there also problems during the day with people visiting the shops. The worst section is between the church and Tesco. There are often large traffic queues, due to parked vehicles and people/deliveries getting in and out of tesco. Three accidents involving/due to parked cars within the last 3 years.
		O Section Control and Control	Clockhouse Rise to existing pedestrian crossing markings./	GM to contact bus company, as PC mention they have had issues here too.



Submission Date: February 2025

(Please remember that the HIP is for new initiatives/measures/schemes in your community – it is NOT to be used as a maintenance log, as these MUST be logged using the online reporting tool via this link https://www.kent.gov.uk/roads-and-travel/report-a-problem)

2	PARK WAY/ASPIAN DRIVE Junction – yellow lines to stop parking blocking junction	Junction being blocked by parked cars	yellow lines to stop parking blocking junction	28/04/25 - This can be done no problem
3.	PARK WAY- Heath Road to Aspian Drive	Parking on blind corner and block bus route	To connect existing lines at Heath Road end and extend past Aspian Drive where Park Way straightens out.	28/04/25 - Generally KCC wouldn't install lines at a location like this unless there is a very robust reason to do so. The DYLs go very far in to the road already Has the bus company made any representations regarding this? GM is happy to contact them and if the bus is being blocked, we can certainly look at lines. Aside from that, visibility looks good and no recorded accidents. 28/04/25 - PC have shared the two below images showing very low visibility at the junction and down the hill. Planners to assess DYLs and GM to contact bus company.



Submission Date: February 2025

(Please remember that the HIP is for new initiatives/measures/schemes in your community – it is NOT to be used as a maintenance log, as these MUST be logged using the online reporting tool via this link https://www.kent.gov.uk/roads-and-travel/report-a-problem)





Submission Date: February 2025

(Please remember that the HIP is for new initiatives/measures/schemes in your community – it is NOT to be used as a maintenance log, as these MUST be logged using the online reporting tool via this link https://www.kent.gov.uk/roads-and-travel/report-a-problem)





Submission Date: February 2025

(Please remember that the HIP is for new initiatives/measures/schemes in your community – it is NOT to be used as a maintenance log, as these MUST be logged using the online reporting tool via this link https://www.kent.gov.uk/roads-and-travel/report-a-problem)

 FORSTAL LANE/MILL	Volume, speed and	Traffic calming measures/large	28/04/25 - GM understands from previous discussions that
LANE	HGV's	vehicle prohibition	HGVs use the estate as a route between B2163 and industrial
		Politically	units.
			We wouldn't be able to install calming, as this is reserved for
		O Adams Creative Group	speeding issues (avg speed above enforcement threshold), but
		FORCE	we can certainly investigate extending the HGV restriction.
		and the state of t	What is the alternative route?
		*OFFICIAL POSTERIAL PROPERTY OF THE PROPERTY O	28/04/25 - GM has explained we wouldnt be able to do a
			physical restrictor, but will explore altering the HGV restriction
			here to include the housing estate.



Submission Date: February 2025

(Please remember that the HIP is for new initiatives/measures/schemes in your community – it is NOT to be used as a maintenance log as these MIIST be logged using the online reporting tool via this link https://www.kent.gov.uk/roads-and-travel/report-a-problem.)

iog, as		u using the omine rep	orthing tool via this link https://ww	w.kent.gov.uk/roaus-and-travel/report-a-problem_j
5	STOCKETT LANE			28/04/25 -
		outside the school	calming solutions outside and near to	
		causing a danger to	Primary School entrance (also	DYLS were offered a year ago at this location alongside a
		pedestrians and	impacting HANOVER ROAD)	package of measures, but the PC said at the time they were not
		vehicle users.		needed. The proposal at the time was to Extend the Double
				yellow lines opposite school for 38m and Install double yellow
				lines next to school zig zags for 6m.
			Stagecoach Performing	
			Arts Maidstone West	28/04/25 - Gm to check with P&A if DYLS are still able to go
			O/GC	ahead. PC have also requested Wig Wags here.
			Beginners2Run	
			Harlequin Out Of School Clubs	
			5. 55.165.165.165.165.165.165.165.165.165.1	
			Felgo	
			Londie	
			Londis Day Tree Fellers	
			hoo	



Submission Date: 30/08/2023

(Please remember that the HIP is for new initiatives/measures/schemes in your community – it is NOT to be used as a maintenance log, as these MUST be logged using the online reporting tool via this link https://www.kent.gov.uk/roads-and-travel/report-a-problem)

Historical Priorities Record -

No	Location	Problem/Concern	What do you feel are the potential solutions?	KCC Comments
	Heath Road	Complaints from residents. Requests for buildouts to	Defer to KCC Highways Planners	Planners comments regarding the build outs: we think it is probably best if we leave the build outs as they are.
	Buildouts	be removed		The guidance we have to follow states that we shouldn't be installing traffic calming on A or B roads, which means our only option would be to remove them. This is very likely to increase the speeds along Heath Road and could lead to unforeseen circumstances.
				If for example we were to remove them, our options are limited to virtual calming and lining, which has a lot less of an effect on speeds. There also doesn't seem to be a pattern of accidents at the build outs, which is the main factor we look at when assessing whether locations are dangerous.
	Heath Road – Either side of the village, entering and exiting.	Horses using highway	Equestrian warning signs	20.10.22 - GM to investigate signage locations and follow through on this. Parish to fund any sign installation.
	Stockett Lane – One at			



Submission Date: 30/08/2023

(Please remember that the HIP is for new initiatives/measures/schemes in your community – it is NOT to be used as a maintenance log, as these MUST be logged using the online reporting tool via this link https://www.kent.gov.uk/roads-and-travel/report-a-problem)

top and one at the			
bottom			
Forstal Lane			
Amsbury Road			
<u>Linton Crossroads</u>	Safety / Air Pollution / Congestion / Improvements required.	Future Scheme in Linton / Loose Parishes.	
Roundabout – Willow Grange	Safety / Air Pollution / Congestion / Improvements required.	Review with Coxheath	
Roundabout – Violet Field	Safety / Air Pollution / Congestion / Improvements required.	Review with Coxheath	
40mph speed limit from 'The Victoria' Heath Road – West side approach.	<u>Traffic Speed</u>	Review with Coxheath and East Farleigh?	Send re
Village Gateways – ES Oct 2020	Average Speed – EF end in particular – see also Future Item D below.	KCC to investigate 1.0m wide gateways with at least 0.5m clearance from edge of Carriageway – 2 No.Heath Road + possibly Stockett Lane & Westerhill Road?	Parish Council to provide exact locations. 20.10.22 PC have measured the space and the required amount of space is not available.
Stockett Lane ME17 4PS Coxheath Primary School Council	Improve road safety measures for school children in the absence of a Crossing Patrol. As meeting with KCC HTW & County Member on site 21st July 23 along with the email G.McN. dated 31	 Bollards on the corner of Hanover Road / Stockett Lane. SLOW markings on road Changing the sign plates from Patrol to say School. Move the warning sign 	22/08/23 – PC to carry out informal consultation on DYLs, GM to raise implementation of moving sign, changing plate to school and tactile paving. 11/10/23 - We can fund the moving of the sign and dropped crossing. PC to decide on whether to fund DYLs. 02/07/24 - Works completed for bollards and signage moving,



Submission Date: 30/08/2023

(Please remember that the HIP is for new initiatives/measures/schemes in your community – it is NOT to be used as a maintenance log, as these MUST be logged using the online reporting tool via this link https://www.kent.gov.uk/roads-and-travel/report-a-problem)

log, as these MUST be logged	using the online repo	rting tool via this link https://www	v.kent.gov.uk/roads-and-travel/report-a-problem
	July 2023 as attached.	down past the parked cars.	
Replacement VAS	Update both Heath Road VAS Sites. The signs are old / worn out and not visible.		Jennie to arrange speed survey. Parish Council to provide location. 20/10/2022 - VAS is a last option and the team responsible for these has said there are no plans to replace this one. What's the problem you are looking to solve with this one? Are there other measures we could take initially? Our data suggests speed limits are well complied with along Heath Rd. There are a few other VAS signs in location, as well as other calming measures. Priority flow section, dragons teeth, high friction and slow markings. ATC to be carried out, arranged by GM. PC to provide exact location details. 5/12/22 - ATC has been carried out, P&A have investigated the results. 80% of drivers complied within the enforcement threshold and average speeds were 30mph. P&A advice is for no further measures at this location.



Submission Date: 30/08/2023

(Please remember that the HIP is for new initiatives/measures/schemes in your community – it is NOT to be used as a maintenance log, as these MUST be logged using the online reporting tool via this link https://www.kent.gov.uk/roads-and-travel/report-a-problem)

log, as th	ese MUST be logged	using the online repo	rting tool via this link https://www	w.kent.gov.uk/roads-and-travel/report-a-problem)
				22/08/23 – We investigated removing the buildouts, but concluded it best to leave them as is. Speeds may increase if these are removed.
	Heath Road – Linton Parish	No controlled crossing to or from the new doctor's surgery across Heath Road – tactile paving and dropped kerbs have alone been installed. However, a "suitable controlled crossing" has not been installed as originally requested by CPC, letter dated 05 March 2018. See the agreed Planning Condition 14 under pedestrian access.	Coxheath Parish Council supports this item in the HIP provided by Linton Parish in 2023. The CPC requests that a safe and "suitable controlled crossing" is installed in line with the Planning Condition 14.	11/10/23 - Site not suitable for a zebra or controlled crossing, ped volume is not high enough. We have installed some elderly people crossing warning signs.
	FORSTAL LANE (East)	Road Surface damaged	Repairs to road surface edges Linked Plumbing Repairs to road surface edges	28/04/25 - Maintenance issues need to be reported via online fault tool.



Submission Date: 30/08/2023

(Please remember that the HIP is for new initiatives/measures/schemes in your community – it is NOT to be used as a maintenance log, as these MUST be logged using the online reporting tool via this link https://www.kent.gov.uk/roads-and-travel/report-a-problem)